#### MMME2104

#### Design & Selection of Mining Equipment Electrical Component


# **DC Machines**

Lecture 8 24 September 2003

# Lecture Outline


- DC Generators
  - Operating principle
  - Separately excited generator
  - Shunt generator
  - Compound generator
- DC Motors
  - Shunt motor
  - Series motor
  - Compound motor
  - Starting and braking
  - Basics of speed control

Generating an AC voltage:




#### Figure 4.1

Schematic diagram of an elementary ac generator turning at 1 revolution per second.



#### Figure 4.2

Voltage induced in the ac generator as a function of the angle of rotation.



#### Figure 4.4

Elementary dc generator is simply an ac generator equipped with a mechanical rectifier called a *commutator*.

#### 

#### Figure 4.5

+20


The elementary dc generator produces a pulsating dc voltage.

The difference between AC and DC generators:

- AC generators use *slip rings*
- DC generators use *commutators*


Otherwise, the machine constructions are essentially the same.

#### Improving the DC output waveform:



#### Figure 4.7

Schematic diagram of a dc generator having 4 coils and 4 commutator bars. See Fig. 4.9.



#### Figure 4.8

The voltage between the brushes is more uniform than in Fig. 4.5.

Induced voltage in a DC generator: E = B L v (Faraday's Law)

For a DC generator, this equation can be manipulated to give:


 $E_o = C n \Phi / 60$ 


- $E_o$  = voltage between the brushes (V)
- N = speed of rotation (rpm)
- $\Phi$  = flux per pole (Wb)
- C = total number of conductors on the armature\*

\*The number of conductors equals the number of slots (coils) times the number of turns per coil times two


Neutral zones:

- Neutral zones are those places on the surface of the armature where the flux density is zero.
- When a generator operates at noload, the neutral zones are located exactly between the poles.
- No voltage is induced in a coil that cuts through the neutral zone.
- We always try to set the brushes so they are in contact with coils that are momentarily in a neutral zone.






#### Armature reaction:




#### Figure 4.14

Magnetic field produced by the current flowing in the armature conductors.




Armature reaction distorts the field produced by the N, S poles.

Shifting the brushes to improve commutation and using commutating poles:






The electromechanical energy conversion process



#### Separately Excited DC Generator



#### Figure 4.17

Separately excited 2-pole generator. The N, S field poles are created by the current flowing in the field windings.

#### No Load Saturation Curves




Figure 4.18a Flux per pole versus exciting current.





Figure 4.18b Saturation curve of a dc generator.


#### Shunt DC Generator

Field winding in parallel with armature




### Shunt DC Generator

Controlling the voltage of a shunt generator:



#### Figure 4.20


Controlling the generator voltage with a field rheostat. A rheostat is a resistor with an adjustable sliding contact.



#### Figure 4.21


The no-load voltage depends upon the resistance of the shunt-field circuit.


### Equivalent circuit of a DC Generator




#### Figure 4.22 Equivalent circuit of a dc generator.

### Separately Excited DC generator under load











#### **Compound DC Generator**



#### **DC Generator Load Characteristics**



#### Figure 4.26

Typical load characteristics of dc generators.

### **DC** Motors

Important DC motor types:

- Shunt Motors
- Series Motors
- Compound Motors


Direct current motors are seldom used in ordinary industrial applications because all electric utilities supply AC. However, for special applications such as in steel mills, mines, and electric trains, it is sometimes advantageous to transform the AC into DC in order to use DC motors. The reason is that the torque-speed characteristics of DC motors can be varied over a wide range while retaining high efficiency.

### DC Motors: Back EMF

Direct current motors are built the same way as generators are; consequently, a DC machine can operate either as a motor or as a generator.

When a motor spins, a voltage is induced in the same manner as a generator. This voltage opposes the motor supply voltage, and is known as *back EMF*:

 $E_o = Cn\Phi/60$ 





#### Acceleration of DC Motors

The net voltage acting on the armature circuit of a DC motor is  $(E_s-E_o)$  volts. The resulting current is limited only by the armature resistance R, and so

$$I = (E_s - E_o)/R$$

When the motor is at rest, the induced voltage  $E_o = 0$ , and so the starting current is

$$Is = E_s/R$$

The starting current produces a powerful starting torque that rapidly accelerates the rotor. As the speed increases, the back EMF increases, with the result that the armature current falls.

The motor continues to accelerate until it reaches the no-load speed. At this speed a back EMF is produced that is slightly less than the supply voltage. The slight voltage difference results in a small *no-load current* that produces sufficient torque to overcome friction.

#### Mechanical power and torque

Power:

We know that  $E_0 = C n \Phi / 60$ .

We also know that the electrical power supplied to the armature is given by:  $\rm P_a$  = E\_s I

Furthermore, the supply voltage is the sum of the back EMF and the resistive drop in the armature:  $E_s = E_o + IR$ 

It follows that  $P_a = E_o I + I^2 R$ 

The I<sup>2</sup>R term represents heat losses in the armature.

The E<sub>o</sub>I term is the electrical power that is converted to mechanical power:

$$P_m = E_o I$$

In reality, the actual mechanical output power is slightly less than Pm due to bearing friction losses, windage losses and armature iron losses.

#### Mechanical power and torque

Torque:

We also know that the mechanical power is given by  $P_m = \pi nT/30$ . Therefore we may write  $\pi nT/30 = Cn\Phi I/60$ 

 $T = C\Phi I/2\pi = K_T I$  where  $K_T = C\Phi/2\pi$ 

 $K_T$  is known as the *torque constant (Nm/A)* of the motor.

This shows that we can increase the torque of the motor either by raising the armature current or by raising the pole flux.

## DC Motors: Speed of Rotation

When a DC motor drives a a load between no-load and full-load, the voltage drop due to armature resistance is always small compared to the supply voltage (IR <<  $E_s$ ). Therefore,  $E_o \approx E_s$ 

So we may write:

$$E_s \approx C n \Phi / 60$$
 or  $n \approx 60 E_s / C \Phi$ 

If the motor speed is expressed in radians per second, we may write:

 $\omega$  = 2 $\pi$  E<sub>s</sub> / C  $\Phi$  = E<sub>s</sub> / K<sub>e</sub>where K<sub>e</sub> = C $\Phi$ /2 $\pi$ 

Ke is known as the speed constant (Vs/rad) of the motor

#### **Torque and Speed Constants**

# When expressed in SI units, the torque and speed constants are exactly the same!

$$K_e = K_T = C\Phi/2\pi$$

## DC Motors: Speed of Rotation

The expressions for motor speed show that the speed of the motor is directly proportional to the armature supply voltage and inversely proportional to the flux per pole. This gives rise to two methods of controlling the speed of DC motors:

- 1. Armature speed control
- 2. Field speed control






Figure 5.7 Armature speed control using a rheostat.



#### Shunt Motor Under Load


- For shunt motors, as the load increases, the speed drops and the armature current (and torque) rises.
- The speed of a shunt motor stays relatively constant from noload to full load – 10-15% drop in small motors, and much less in large motors.
- Of course, via field control the speed can be kept constant regardless of load.



#### Series DC Motors

A series DC motor is identical in construction to a shunt motor except for the field winding. The field is connected in series with the armature and must therefore carry the full armature current.

Therefore the series field winding is normally composed of a few turns of wire with cross section large enough to carry he current.




#### Series DC Motors

- The properties of a series motor are completely different from those of a shunt motor.
- In a shunt motor, the flux per pole is constant at all loads because the shunt field is connected directly to the supply. In a series motor, the flux per pole depends upon the armature current and hence the load.
- When a series motor operates at full load, the flux per pole is the same as that of a shunt motor of identical power and speed.
- When the series motor starts, the armature current is higher than normal AND the flux per pole is higher than normal. Therefore series motors have extremely high starting torque.
- Conversely, when the motor operates below full load, the armature current and pole flux are both smaller. The weaker field causes the speed to rise much higher than normal.

#### Series vs Shunt DC Motors

Torque vs speed and current for Shunt and Series DC Motors




### **Compound DC Motors**


A compound DC motor carries both a series field winding and a shunt field winding.

The two fields are oriented so they add.

Therefore as the load increases, the speed decreases – much more than it would for a plain shunt motor – typically 10-30%.



#### Compound vs Series vs Shunt DC Motors




#### Figure 5.13

Typical speed versus torque characteristics of various dc motors.

#### Reversing the Direction of Rotation of a DC Motor

To reverse the direction of rotation of a DC motor, we must either:

- Reverse the armature connections
- Reverse both the shunt and series field connections



#### Figure 5.15

- a. Original connections of a compound motor.
- b. Reversing the armature connections to reverse the direction of rotation.
- c. Reversing the field connections to reverse the direction of rotation.

# Starting a DC Motor

- If we apply full voltage to a stationary motor, the starting current in the armature will be very high (20-30 times the nominal load current) and we run the risk of:
- Burning out the armature
- Damaging the commutator and brushes, due to heavy sparking
- Overloading the supply
- Breaking the shaft due to mechanical shock
- Damaging the driven equipment due to the sudden torque surge


All DC motors must therefore be provided with a means to limit the starting current to reasonable values.

# Stopping a DC Motor

There are three ways to brake a DC motor:

- Mechanical (friction) braking
- Dynamic braking
- Plugging

### **Dynamic Braking**







Figure 5.17a Armature connected to a dc source  $E_s$ .

Figure 5.17c Dynamic braking.

# Plugging







Figure 5.19a Armature connected to dc source  $E_{\rm s}$ .

Figure 5.19b Plugging.

## **Comparison of Braking Methods**




#### Figure 5.18


Speed versus time curves for various braking methods.


#### Armature Reaction in DC Motors

The current flowing in the armature creates a magnetic field that distorts and weakens the flux coming from the poles.

- Armature reaction can cause poor commutation (sparking) and also pole tip saturation.
- Commutating poles are used to cancel the armature reaction at the neutral point.











#### **Basics of Variable Speed Control**



#### **Realistic Torque-Speed Curve**




#### Permanent magnet motors


Instead of using a field winding, permanent magnets can be used to establish the field.

- By using magnets, the energy consumed, the heat produced, and the volume of the motor is reduced.
- Furthermore, magnets increase the effective air gap (since magnets have permeability similar to air). This has two benefits:
- 1. The armature reaction effects are minimised
- 2. The inductance of the armature reduces, giving the motor better transient response.

The drawback of permanent magnet motors is the high cost of the magnets and the inability to weaken the field.



**Figure 5.24** Six-pole dc motor having a compensating winding distributed in slots in the main poles. The machine also has 6 commutating poles. (*Courtesy of General Electric Company*)



#### Figure 4.30

Armature of a dc generator showing the commutator, stacked laminations, slots, and shaft. (Courtesy of General Electric Company, USA)





Figure 4.36 Sectional view of a 100 kW, 250 V, 1750 r/min 4-pole dc generator. (Courtesy of General Electric Company, USA)



#### Figure 5.30

Permanent magnet motor rated 1.5 hp, 90 V, 2900 r/min, 14.5 A. Armature diameter: 73 mm; armature length: 115 mm; slots 20; commutator bars: 40; turns per coil: 5; conductor size: No. 17 AWG, lap winding. Armature resistance at 20°C: 0.34 Ω.

(Courtesy of Baldor Electric Company)