

1

ELECTRICAL MACHINES 2010

1] What's the Electricity?

It's a type of Energy can do works.

2] What are the applications of Electricity? Give some Examples?

Electricity is very important for our life so that it's used in

- i) For Transport (Metro)
- ii) For Industry
- iii)


3] When Electricity discovered?

Electricity discovered From 400 years.

4] What are the different types of Electricity "Electrical Energy"?


i - Alternating current (AC)

Current's Alternating with time.



ii - Direct current (DC)

Current's constant with time.



5] what are the factors required to generate (produce) Electricity?

i] Magnetic Energy "Magnet"

a) Natural Magnet


1) There are types of rocks contain on magnetic field this Rock called "Magnetic Rocks"

2) Have constant Energy (Power)

b) Artificial Magnet. (Electrical magnet)

When current pass through coil of iron coils, it'll generate magnetic field.

2) Have variable Energy




ii] Mechanical Energy "Motion"

The most contributing source

المحرك - مصدر طاقة في توليد الكهرباء

motion

iii] Electrical conductors:



6] What are the different types of materials from the Electricity point of view?

i) Conducting materials (Fe - Al - Cu)

- metallic materials - تسمح بمرور التيار الكهربائي بسهولة جدا لها

ii) Insulating materials (Wood - Plastic - Rubber)

- لا تسمح بمرور التيار الكهربائي بسهولة

iii) Semi conducting materials (Germanium, Silicon)

7) What are the different sources of Energy used to produce electricity?

A) Conventional sources مصادر تقليدية

1) Water Power (Energy) :

- Natural

Falls سقوط المياه

- Artificial

Dams سدود

When the potential energy is used to make the water run down to move and rotate the rotor (shaft) of the generator.

2) Fuel Energy:

- Solid (Wood, ~~Coal~~ Coke) High Calorific Value

- Liquid (Petroleum, Solar, Gas) medium Calorific Value

- Gas (Natural Gas) Low Calorific value

where the heat produced from burning the fuel is used to add heat to boiling (Boiler) to change water to water steam with high pressure, to drive and move the steam turbine to rotate the rotor (shaft) of the generator.

3) Atomic (Nuclear) Energy.

(Plutonium - Uranium)

B) Un Conventional sources مصادر غير تقليدية

1) Solar Energy

الطاقة الشمسية

2) Wind Energy

طاقة الرياح

3) Wave Energy

طاقة الأمواج

4) Tide Energy

طاقة المد والجزر

8) What are the effects of an electrical current passing through a conductor?

1) Heat effect. ($= I^2 \cdot R$ watt), where, I is the current passing through conductor (A) and R is the resistance (Ω)

2) Magnetic Field.

Magnetic field generated around and along the conductor when current pass through it

شدة المجال المغناطيسي تتناسب مع قيمة التيار المار في الموصل

9) What are the main parts of magnetic circuit? and what's the function of each part?

1- Electrical power source:


Give Electrical power to the circuit

(volt - current)

Source

I

coil



2- COIL ::

To convert the electrical power to magnetic power

3- Iron Core ::

To Transport and control the magnetic energy produced.

10) Why all the cores of different types of machine are made from iron?


- Why all the electrical machines have an Iron Core?

The Iron core has a very low resistance for pass a magnetic flow, less the Air

5

Q1) What are the main parts (elements) of Electrical circuit?

- 1- Source of Current
- 2- Load [Resistance - Inductance - Capacitance].
- 3- Switch



Q2) What are the different types of electrical machines?

A) According to the type of power:


- 1) AC machines
- 2) DC machines

B) According to the type of motion

- 1) static machines (Transformer)
- 2) dynamic machines (motor, generator)

Transformer

- Transformer is an AC-Static Machine which transforms electric power from one Alternating circuit to another without change in frequency.



If $N_2 > N_1 \Rightarrow V_2 > V_1$
 Step UP transformer
 $a > 1$

If $N_2 < N_1 \Rightarrow V_2 < V_1$
 Step down transformer
 $a < 1$

$$a = \frac{N_2}{N_1}$$

- Φ :- Flux field
- B :- Flux density
- H :- magnetic field strength
- V :- Voltage
- N :- No. of turns
- I :- Current
- $\frac{V}{N}$:- Voltage per turn
- a :- Transformation ratio

$\frac{V_1}{N_1} = \frac{V_2}{N_2}$ - إذا كان المحول ذو نوى مغناطيسية فإنه يولى تياراً عكساً

$\uparrow N_1, V_2 \downarrow \Rightarrow \downarrow N_2, V_1 \uparrow$ - إذا كان المحول خاضعاً للمغناطيسية فإنه يولى تياراً عكساً

$$\frac{N_1}{N_2} = \frac{V_1}{V_2} = \frac{I_2}{I_1} \quad ; \quad P_1 = V_1 I_1, \quad P_2 = V_2 I_2$$

For ideal transformer $P_1 = P_2 \Rightarrow V_1 I_1 = V_2 I_2$

$$\frac{V_1}{V_2} = \frac{I_2}{I_1}$$


$$\Rightarrow a = \frac{N_2}{N_1} = \frac{V_2}{V_1} = \frac{I_1}{I_2}$$

Q3) What are the main parts of single phase transformer? what's the function of each part?

1- Primary insulated coil
 Converts Electrical power to Magnetic power

2- Insulated Iron core
 Transport magnetic field and control the magnetic energy

3- Secondary coil
 Converts magnetic power to Electrical power



7

14) What are the different types of transformer?

a) According to Voltage :-


- 1- Step up transformer
- 2- Step down transformer

b) According to Construction

1- Core type transformer :-

The magnetic flux take long time to transform primary to secondary coil, because two coils are at different core


- High iron losses
- Low efficiency



2- Shell type transformer :-

All magnetic flux cutting the secondary coil in quick time because the two coils are in the same core


- Low losses
- High efficiency



3- Auto transformer

Consist of one coil only

- High efficiency
- Low volumetric size
- Used in small power only



8

c) According to No. of phases :-

- 1- Single phase transformer
- 2- Three-phase transformer

d) According to rating of power :-

- 1- Very large power transformer
- 2- Large power transformer
- 3- medium power transformer
- 4- Distribution power transformer
- 5- Electronic power transformer

15] What are the different types of losses in transformer and how to reduce them?

1) Copper Losses (Heat Losses) :-

$$\text{Cu-losses} = \text{H-losses} = I_1^2 R_1 + I_2^2 R_2$$

2) Iron Losses

a) Residual Losses

عن مرور الفيض المغناطيسي في الـ (Core) فإن جزءا منها يبقى فيه

b) ED current

To Reduce losses :-


- 1) Select material has a low resistance.
- 2) Add Silicon to Iron to provide through of magnetic field on Iron core.

16] efficiency on any machine :-

$$\eta = \frac{\text{O/P}}{\text{I/P}} = \frac{\text{I/P} - \text{Losses}}{\text{I/P}} = \frac{\text{O/P}}{\text{O/P} + \text{Losses}}$$

Q7] With the help of simple line diagram show the different methods of connection of 3-phase system? write the equation of 3-phase system?
 - with the help of simple diagrams show the different connections of 3-phase transformer?




I) Delta Connection (Δ)



بدراسة تقاربية


$V_L = V_{ph}$

$I_L = \sqrt{3} I_{ph} = \sqrt{3} \frac{I_L}{\sqrt{3}}$



$P_{3-\phi} = 3 V_{ph} I_{ph} = 3 V_L \cdot \frac{I_L}{\sqrt{3}} = \sqrt{3} V_L I_L$

II) Star connection (Y)



نوع التلاص
نقاط في
نقطه واحدة

$I_L = I_{ph}$

$V_L = \sqrt{3} V_{ph}$

$P_{3-\phi} = \sqrt{3} V_L I_L$

Star connection اشد من A

التيار في التوازي لا يوجد
 في التوازي في أي وجه يسير وقد
 يسبب مشاكل

18) What are the basic operation of Electrical Motor?

19) What are the different types of electrical motors give some Application?

1- DC Motors:-

Single phase motor.

2- AC Motors:-

1- Single phase motor.

2- 3 phase motor.

DC Machines

Φ :- Flux Weber (Wb)

A :- cross section area m^2

I :- current A

B :- flux density Tesla wb/m^2

μ :- Permeability



H :- Magnetic field strength AT/m

N :- No. of turns Ta


l :- length of coil m

V :- velocity of core

$e = B l V$




B-H curve



*** Function of Pole shoe**

- 1- تثبيت الملفات
- 2- هي جزء من الدائرة المغناطيسية
- 3- تجعل المغناطيسية ذات شدة ثابتة ومنظمة



*** Function of Frame (Yoke)**

- 1- تثبيت اجزاء الماكينة
- 2- هو جزء من الدائرة المغناطيسية
- 3- يمس الاجزاء الداخلية للماكينة

*** Derivation:**

$$E = D \phi V = \frac{\phi}{A} \cdot l \cdot \frac{2\pi n r}{60}$$

$$A = \frac{2\pi r l}{p}$$

$$\therefore E = \frac{\phi p}{2\pi r l} \cdot l \cdot \frac{2\pi n r}{60}$$

$$E = \frac{\phi n p}{60} \cdot \frac{Z}{a}$$

$$E_g = \frac{Z \phi n p}{60 a}$$

- p = No. of Poles
- n = r.p.m Speed
- Z = Total no. of conductors
- a = No. of parallel paths

$$Z = 2N$$

* لفة الملفات

1) Lap


$$a = p$$

$$2) \text{Wave } a = 2$$

*** Voltage Regulation**

$$\frac{E_g - V_t}{V_t} \times 100\%$$


Types of Generator



shunt \equiv Parallel

* shunt \equiv Parallel

- $I_f \Rightarrow$ Field current.
- $I_a \Rightarrow$ Armature current.
- $I_L \Rightarrow$ Load current.
- $R_a \Rightarrow$ Armature winding Resistance.
- $R_f \Rightarrow$ Field winding resistance.
- $V_t \Rightarrow$ Terminal voltage.



- $E_g \Rightarrow$ E.M.F.
- $I_a = I_f + I_L$
- $V = I R$
- $P_{in} \Rightarrow$ Input power
- $P_o \Rightarrow$ output power

$$I_f = \frac{V_t}{R_f} \quad \bullet \quad V_t = E_g - I_a R_a$$

$$P_{in} = E_g I_a + W \quad P_o = V_t I_L$$

* Generator efficiency:

$$\eta = \frac{P_o}{P_{in}} \times 100\% = \frac{P_o}{P_o + \text{loss}} \times 100\% = \frac{P_{in} - \text{loss}}{P_{in}}$$

Losses = $P_a + P_f + W$ - stray losses

$$P_a = I_a^2 R_a \quad P_f = I_f^2 R_f$$

How to get max. efficiency :- η_{max}

Const. loss = Variable losses

$$P_f + W = P_a$$

$$I_f^2 R_f + W = I_a^2 R_a$$

$$I_a)_{\eta_{max}} = \sqrt{\frac{P_f + W}{R_a}}$$

How to get stray losses :- (W) :-


By running any machine as a motor & on No Load.

For Motor

$$P_{out} = E_g I_a - W$$

$$E_g I_a = W$$

$$P_{in} = V_t I_L$$




DC - Motor

$$I_a = I_L - I_f$$

$$E_g I_a - W = P_{out}$$


$$P_{in} = V_t I_L$$



* Build up process in Self excited Generator

- Build up requires (Requirements)

1. There must be ~~some~~ some residual magnetic effect in the field poles.
2. The flux produced by the initial exciting currents must assist the residual flux.
3. The field resistance must be below the critical resistance.
4. The speed must be above the critical speed.



* Drive the torque equation for DC shunt motor:-


$$F = BIl$$

$$F = \frac{Z\phi}{2\pi a} I_a l_a$$

$$F = \frac{Z\phi P}{2\pi r} \frac{I_a}{a} \left\{ = \frac{Z\phi P I_a}{2\pi r a} \right.$$

$$T = F \cdot r = \frac{Z\phi P}{2\pi r} \frac{I_a}{a} \cdot r$$

$$\therefore T = \frac{Z\phi P}{2\pi} \frac{I_a}{a}$$




* Torque current ratio for DC Motor :-

$$T = \frac{Z \Phi P I_a}{2\pi a}$$

$\therefore Z$ & P & $2\pi a$ are const

$$\therefore \text{get } \frac{ZP}{2\pi a} = K$$

$$\therefore T = K \Phi I_a$$



For series motor :-

$$T \propto \Phi I_a \quad \& \quad I_a \propto \Phi$$

$$\therefore T \propto I_a^2 \quad (\text{parabolic})$$

For shunt motor :-

$$\Phi = \text{const}$$

$$\therefore T \propto \text{const} \cdot I_a \Rightarrow T$$

$$T \propto I_a \quad (\text{linear})$$

Example. 1

A 20 kW shunt generator with a terminal voltage (V_t) of 250 V. The armature winding has a resistance 0.05Ω and field resistance 100Ω . Calculate the EMF in the armature.

Solution

$$P_o = 20 \text{ kW} = 20 \times 10^3 \text{ W}$$

$$V_t = 250 \text{ V}$$

$$R_a = 0.05 \Omega$$

$$R_f = 100 \Omega$$

$$I_f = \frac{V_t}{R_f} = \frac{250}{100} = 2.5 \text{ A}$$

$$P_o = I_L \times V_t$$


$$I_L = \frac{P_o}{V_t} = \frac{20 \times 10^3}{250} = 80 \text{ A}$$

$$I_a = I_L + I_f = 80 + 2.5 = 82.5 \text{ A}$$

$$E_g = V_t + I_a R_a$$

$$E_g = 250 + (82.5 \times 0.05)$$

$$E_g = 254.125 \text{ V}$$



$$E_g = V_t + I_a R_a$$

$$V_t = I_f R_f$$

$$I_f = \frac{V_t}{R_f}$$

$$P_o = I_L V_t$$

$$I_a = I_L + I_f$$

Example 2

A Generator is run as a motor on No Load with an input current of 7.8 A. A terminal voltage of 500 V. If the shunt field resistance is 200 Ω and the armature resistance is 0.43 Ω . Calculate the stray losses.

Solution

Motor on No Load

$$P_f + W = P_o \quad W = E_g I_a$$


$$I_L = 7.8 \text{ A}$$

$$V_t = 500 \text{ V}$$

$$R_f = 200 \Omega$$

$$R_a = 0.43 \Omega$$

$$W = ??$$



$$W = E_g I_a$$

$$I_f = \frac{V_t}{R_f} = \frac{500}{200} = 2.5 \text{ A}$$

$$I_a = I_L - I_f = 7.8 - 2.5 = 5.3 \text{ A}$$

$$E_g = V_t - I_a R_a = 500 - (5.3 \times 0.43)$$

$$E_g = 489.979 \text{ V} \approx 497.721 \text{ V}$$

$$W = E_g I_a = 497.721 \times 5.3$$

$$W = 2637.9 \text{ W} \approx 2.6 \text{ kW}$$

$$W = P_o - P_f = E_g I_a$$

$$P_f = I_f^2 R_f$$

$$I_f = V_t / R_f = \dots$$

$$I_a = I_L - I_f = \dots$$

$$P_o = E_g I_a$$

$$E_g = V_t - I_a R_a$$

Example 2

A 10 kW, 250V, DC-shunt Motor has a armature resistance 0.39Ω , a shunt field resistance 200Ω and stray losses of 200 W . Calculate


- 1) Efficiency for an input of 11 kW .
- 2) Load for max efficiency.
- 3) max efficiency.

Solution

$$P_m = 10 \text{ kW} \quad V_t = 250 \text{ V}$$
$$R_a = 0.39 \Omega \quad R_f = 200 \Omega$$
$$W = 200 \text{ W}$$

Q. 1) $P_{in} = 11 \text{ kW}$

Q. 2) $I_a)_{\eta_{max}}$ 3) η_{max}



$$\eta = \frac{P_o}{P_{in}} = \frac{P_m - \text{loss}}{P_{in}}$$

$$P_m = V_t I_L \Rightarrow I_L = \frac{11 \times 10^3}{250} = 44 \text{ A}$$

$$I_f = \frac{V_t}{R_f} = \frac{250}{200} = 1.25 \text{ A}$$

$$\text{Loss} = I_a^2 R_a + I_f^2 R_f + W$$

$$11 \times 10^3 = (44 - 1.25)^2 \times 0.39 + (1.25)^2 \times 200 + 200$$

$$\text{Loss} = 1067.54 \text{ W}$$

$$\therefore \eta = \frac{11 \times 10^3 - 1067.54}{11 \times 10^3} \text{ about } \Rightarrow \boxed{\eta = 90\%} \Rightarrow \textcircled{1}$$

$$I_a)_{\eta_{max}} = \sqrt{\frac{P_f + W}{R_a}} = \sqrt{\frac{I_f^2 R_f + W}{R_a}} = \sqrt{\frac{1.25^2 \times 200 + 200}{0.39}}$$

$$\boxed{I_a)_{\eta_{max}} = 36.3 \text{ A}} \Rightarrow \textcircled{2}$$